EXHIBIT I

Failures above the base plate are being studied by the TIA committee.